

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 4: WEED NOT MAINTAINED PROPERLY THROUGHOUT LOCATION. MAINTAIN WEEDS IN ACCORDANCE WITH RULE 606.		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Type: Bradenhead		# 1	
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Vertical Separator		# 1	
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment		# 1	
Comment:			
Corrective Action:			Date:
Type: Prime Mover		# 1	
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked		# 4	
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity		# 1	
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run		# 1	
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 272243 Type: WELL API Number: 071-08058 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: OPPERATOR SUBMITTED MIT ON 11/29/2022

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/05/2015 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 IS ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: ROW SOUTH WEST OF LOCATION ON THE HILL HAS STARTED ERODDING DUE TO RESENT SEVERE STORMWATER EVENTS. REPAIR AND MAINTAIN BMP'S AT ALL TIMES.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 278528 Lat: 37.144593 Long: -104.697074

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action Date: _____

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695108956, CA HAS BEEN ADDRESSED.	beardslt	09/10/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695110238	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6701065