

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2024

Submitted Date:

09/11/2024

Document Number:

693807709

FIELD INSPECTION FORMLoc ID 322495 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10770

Name of Operator: VISION ENERGY LLC

Address: P O BOX 370

City: IGNACIO State: CO Zip: 81137

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bechtolt, Phoebe	970-563-4000	pbechtolt@maralexinc.com	
Labowskie, Steve		steve.labowskie@state.co.us	
O'Hare, Mollie	970-563-4000	mollieo@maralexinc.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Graves, Jim	970-712-0099	mrinc20@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210630	WELL	TA	07/01/2021	GW	045-06386	CALF CANYON-FEDERAL 26-1	TA

General Comment:

ECMC staff performed a routine field inspection on 9/4/2024.
 Issues were found requiring corrective action. See inspection text and photos for details.
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<u>Lease Road:</u>			
Type	Main		
comment:			
Corrective Action		Date:	
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<u>Signs/Marker:</u>			
Type	TANK LABELS/PLACARDS		
Comment:	ign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	10/11/2024
Type	WELLHEAD		
Comment:	Sign at tank battery. Sign not updated to reflect current operator		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	10/11/2024
Emergency Contact Number:			
Comment:	970-858-8550		
Corrective Action:			Date: _____
<u>Good Housekeeping:</u>			
Type	WEEDS		
Comment:	Weeds inside tank berms and around separator.		
Corrective Action:	Comply with Rule 1003.f.	Date:	10/11/2024
Overall Good: <input checked="" type="checkbox"/>			
<u>Spills:</u>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<u>Fencing/:</u>			
Type	TANK BATTERY		
Comment:	Hogwire and T-post		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hogwire and T-post		
Corrective Action:		Date:	
<u>Equipment:</u>			
Type: Bradenhead		# 1	corrective date

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		39.515924,-108.740843	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 210630

Type: WELL

API Number: 045-06386

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: Last MIT to maintain SI/TA status 12/19/2020

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/26/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 250

Fluid Type: GAS

End Surf Csg Pressure: 25

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807710	Inspection photos 9/4/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6701634