

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2024

Submitted Date:

09/11/2024

Document Number:

710500362

**FIELD INSPECTION FORM**Loc ID 333534 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217810	WELL	PR	11/01/2021	CBM	071-06589	Chinamans Federal 24-19	EI
263628	PIT	AC			-	CHINAMANS CANYON 24-19	EI
270338	WELL	PR	12/29/2004	GW	071-07941	Chinamans Federal 24-19 Tr	EI
278527	PIT	AC			-	CHINAMANS CANYON 24-19 ONSITE	EI

**General Comment:**

This is an Environmental Inspection for the Chinamans Federal 24-19 and Chinamans Federal 24-19 TR, well locations located in Las Animas County CO.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Lease road has Russian Thistle, "Tumbleweed", growing down the center of the Right-of-Way.			
Corrective Action	L	Maintain weeds per Rule. 606	Date:	10/25/2024
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	Placard on meter house			Date: _____
Corrective Action:				
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Weeds Russian Thistle, "Tumbleweed", throughout location.			
Corrective Action:	Maintain weeds per Rule 606.		Date:	10/25/2024
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:			Date:	
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	217810	Type:	WELL	API Number:	071-06589	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	263628	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	270338	Type:	WELL	API Number:	071-07941	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	278527	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 263628Lat: 37.238262Long: -104.715645

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment: Pit ID 263628 is active on location

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective

Date: \_\_\_\_\_

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective

Date: \_\_\_\_\_

Type: Produced WaterLined: NOPit ID: 278527Lat: 37.238262Long: -104.715645

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment: Debris inside pit

Corrective

Remove debris per Rule 606.

Date: \_\_\_\_\_

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective

Date: \_\_\_\_\_

Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:	
Comment:			
Corrective			
Permit:	Facility ID	Permit Num	Expiration Date
	278527	403746610	
	263628	1325841	
	263628	403746569	
	278527	1175492	

Date:

**ECMC Comments**

Comment	User	Date
<a href="#">This is a Field inspection in response to Form 15 Document #'s 403746569 and 403746610</a>	sanchezcc	09/12/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500363	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6703472">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6703472</a>