

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2024

Submitted Date:

09/12/2024

Document Number:

693807735

FIELD INSPECTION FORM

Loc ID: 322533 Inspector Name: BROWNING, CHUCK On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Bechtolt, Phoebe	970-563-4000	pbechtolt@maralexinc.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
O'Hare, Mollie	970-563-4000	mollieo@maralexinc.com	
Graves, Jim	970-712-0099	mrinc20@maralexinc.com	
Gross, Jason		jgross@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210737	WELL	SI	02/01/2007	GW	045-06495	MESAGAR (FEDERAL) 3-1	TA

General Comment:

ECMC staff performed a routine field inspection on 9/5/2024.
Issues were found requiring corrective action. See inspection text and photos for details.
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Main		
comment:			
Corrective ActionL		Date:	
Type	Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not legible Sign not updated to reflect current operator		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	10/11/2024
Emergency Contact Number:			
Comment:	Sign not legible Sign not updated to reflect current operator		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	10/11/2024
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds grown up around wellhead		
Corrective Action:	Comply with Rule 606	Date:	10/11/2024
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	Hogwire & T-post		
Corrective Action:		Date:	
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210737 Type: WELL API Number: 045-06495 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well listed as SI, but is actually TA.
Last reported production 1/1/2007. No MIT on record.
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Date: 10/11/2024

BradenHead

Date of Last Brhd Test: 09/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 17 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Brhd test due by 9/27/2024

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: _____ Pit ID: _____ Lat: 39.468406 Long: -108.657647

Reference Point: SE Other: _____ Length: 20 Width: 20

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807736	Inspection photos 9/5/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6703584