

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2024

Submitted Date:

09/06/2024

Document Number:

715200820

FIELD INSPECTION FORM

Loc ID 334274 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General	713-209-4000	FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216091	WELL	PR	07/01/2013	CBM	067-07697	HUBER-KAIME 1-12U	PR

General Comment:

[SE Compliance Specialist Brian Welsh](#) conducted a routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Gravel road off of CR 510 across private ranch access		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on separator		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign at location entrance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Landowner is storing vehicles and misc debris on west and south edge of location. See attached photos		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence along north edge of location		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal cage around gear box		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Not all deadmen are marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: <u>09/27/2024</u>
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access for both wells		

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	1-Meter run in metal separator shed for Huber Kaime 1-12U. Calibration shows 8/12/24 1-Meter run for Huber-Kaime 3-12U on west side of separator. Calibration shows 4/26/24		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Electric panel, control panel and phase convertor on southeast corner of location. Telemetry equipment at separator		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 114 for Huber Kaime 1-12U. Lufkin 320 for Huber Kaime 3-12U		
Corrective Action:		Date:	
Type: Compressor	# 0		
Comment:	Compressor removed from location. Compressor shed still on location at time of inspection		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric motors		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:	1-Vertical heated separator with metal shed and built in liquid storage on north side of location (East separator for Huber Kaime 1-12U) 1-Vertical heated separator with metal shed on north side of location. (West separator for Huber Kaime 3-12U)		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Bird protector on separator stacks		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216091 Type: WELL API Number: 067-07697 Status: PR Insp. Status: PR

Producing Well

Comment: Well is PR at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/10/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Fail	Gravel	Pass			
Gravel	Pass					

Comment: [Erosion on access from private road has erosion](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 09/27/2024

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Operator needs to seek variance for landowner storing misc equipment and debris on edge of location	welshb	09/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403912339	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695885
715200924	location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695882