

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2024

Submitted Date:

09/13/2024

Document Number:

715200946

**FIELD INSPECTION FORM**Loc ID 338289 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| Dolezal, Pat |       | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 295016      | WELL | PR     | 01/14/2014  | GW         | 125-11176 | OSMUS 31-2    | PR          |

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

**Location**

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Lease Road:</b> |  |       |  |
| Type               | Access   |       |  |
| comment:           | Access location from CR 23.5 and CR 24 through farm ground and along edge of pasture |       |  |
| Corrective Action  |  | Date: |  |

Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             | Lease sign mounted to meter shed. Sticker is peeling off and needs replaced |       |  |
| Corrective Action:   |   | Date: |  |

|                           |                      |                      |  |
|---------------------------|----------------------|----------------------|--|
| Emergency Contact Number: |                      |                      |  |
| Comment:                  | <input type="text"/> |                      |  |
| Corrective Action:        | <input type="text"/> |                      |  |
|                           | Date:                | <input type="text"/> |  |

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |                                       |       |  |
|--------------------|---------------------------------------|-------|--|
| <b>Fencing/:</b>   |                                       |       |  |
| Type               | PUMP JACK                             |       |  |
| Comment:           | Metal panels around unit and wellhead |       |  |
| Corrective Action: |                                       | Date: |  |

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Ancillary equipment | # 2   |       |                 |
| Comment:                  | Telemetry equipment and gas scrubber            |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Pump Jack           | # 1   |       |                 |
| Comment:                  | Zhongyuan unit                                  |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Gas Meter Run       | # 1   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Vertical Separator  | # 1   |       |                 |
| Comment:                  | Vertical gas separator 50% buried by meter shed |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Prime Mover         | # 1   |       |                 |
| Comment:                  | Kohler gas engine                               |       |                 |
| Corrective Action:        |   | Date: |                 |



| Inspected Facilities |                              |       |      |             |           |         |    |               |    |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 295016                       | Type: | WELL | API Number: | 125-11176 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                              |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production |       |      |             |           |         |    |               |    |
| Corrective Action:   |                              |       |      | Date:       |           |         |    |               |    |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

|              |                |   |
|--------------|----------------|---|
| Document Num | Description    | URL   |
| 715200947    | location photo | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6706173">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6706173</a> |