

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403871737

Date Received:

07/31/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 684901439

Inspection Date: 06/08/2016

FIR Submit Date: 06/08/2016

FIR Status: ACTION REQUIRED

#### Inspected Operator Information:

Company Name: EOG RESOURCES INC

Company Number: 27742

Address: 600 17TH ST STE 1100N

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 414174

Location Name: ELMER Number: 8-31H County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 31 Twp: 12N Range: 62W Meridian: 6

Latitude: 40.959825 Longitude: -104.361350

#### FACILITY - API Number: 05-123- -00 Facility ID: 414174

Facility Name: ELMER Number: 8-31H

Qtrqtr: SWSE Sec: 31 Twp: 12N Range: 62W Meridian: 6

Latitude: 40.959825 Longitude: -104.361350

### CORRECTIVE ACTIONS:

1 CA# 50392

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 07/08/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.

ECMC Decision: \_\_\_\_\_

ECMC Representative:			
----------------------	--	--	--

  

<b>2</b>	<b>CA# 50393</b>		
Corrective Action:		Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.	Date: <u>07/08/2016</u>
Response:		CA COMPLETED	Date of Completion: <u>07/26/2024</u>
Operator Comment:		Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.	
ECMC Decision: _____			
ECMC Representative:			

  

<b>3</b>	<b>CA# 50394</b>		
Corrective Action:		Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date: <u>09/08/2016</u>
Response:		CA COMPLETED	Date of Completion: <u>07/26/2024</u>
Operator Comment:		Operator has addressed and removed the unused frac tank identified onsite to comply with the 600 series.	
ECMC Decision: _____			
ECMC Representative:			

  

<b><u>OPERATOR COMMENT AND SUBMITTAL</u></b>	
Comment:	CA follow-up has been completed for this location.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Ashley Noonan</u>	Signed: _____
Title: <u>Sr Regulatory Analyst</u>	Date: <u>7/31/2024 8:14:52 AM</u>

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403871737	FIR RESOLUTION SUBMITTED
403871750	Inspection Report Resolution

Total Attach: 2 Files