

Operator: 8 NORTH

Location Name: WILSON 1160-29-22

Loc ID: 415293

Inspection: 696301576







CA: Produced Water Tank - Missing Capacity and NFPA is fading, see photos. Comply with Rule 210.d.

CA Resolution: Operator has appropriately installed NFPA and capacity labels on the produced water tank.

CA: Stained Soil at Wellhead, see photos. Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.