

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 24-6 (F24W) Pad

Location #: 334693



Photo # 46 From Entrance to location



Photo # 47 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 24-6 (F24W) Pad

Location #: 334693



Photo # 48 Location



Photo # 49 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY 24-6 (F24W) Pad
Location #: 334693



Photo # 50 Location



Photo # 51 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 24-6 (F24W) Pad

Location #: 334693



Photo # 52 Location



Photo # 53 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 24-6 (F24W) Pad

Location #: 334693



Photo # 54 Location



Photo # 55 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 24-6 (F24W) Pad

Location #: 334693




Photo # 56 Rupture disc vent line does not comply with CECMC pressure safety device rules.



Photo # 57 Rupture disc vent line does not comply with CECMC pressure safety device rules.