

Inspection Photos

Location Name: CAERUS PICEANCE LLC Mamm Creek J6SEB Pad

Location #: 432265



Photo # 8626 From Entrance to location



Photo # 8627 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Mamm Creek J6SEB Pad

Location #: 432265



Photo # 8628 Location



Photo # 8629 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Mamm Creek J6SEB Pad

Location #: 432265



Photo # 8630 Location



Photo # 8631 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Mamm Creek J6SEB Pad

Location #: 432265



Photo # 8632 Location



Photo # 8633 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC Mamm Creek J6SEB Pad

Location #: 432265



Photo # 8634 Location



Photo # 8635 Label on chemical tank peeling & some info is illegible/does not comply with CECMC rules



Inspection Photos

Location Name: CAERUS PICEANCE LLC Mamm Creek J6SEB Pad

Location #: 432265



Photo # 8636 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 8637 PRV vent line does not comply with CECMC pressure safety device rules