

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



Photo # 523 From entrance to location



Photo # 524 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



Photo # 525 Location



Photo # 526 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



Photo # 527 Location

Photo # 528 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



Photo # 529 Unmarked deadman



Photo # 530 Same unmarked deadman


## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



**Photo # 531 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 532 PRV vent line does not comply with CECMC pressure safety device rules**