

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2024

Submitted Date:

09/16/2024

Document Number:

713301114

FIELD INSPECTION FORM

Loc ID 319094	Inspector Name: Kester, Michael	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: <div style="border: 1px solid black; padding: 2px;"> 45 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested </div>
Operator Information: ECMC Operator Number: <u>10459</u> Name of Operator: <u>EXTRACTION OIL & GAS INC</u> Address: <u>555 17TH STREET SUITE 3700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CivitasResources		Inspections@civiresources.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242874	WELL	PA	09/25/2017	OW	123-10665	MEIKLE 28-1	PA
453223	WELL	PR	09/08/2018	OW	123-45983	Coyote Trails 34S-20-12N	PR
453224	WELL	PR	10/06/2018	OW	123-45984	Coyote Trails 34S-20-14C	PR
453225	WELL	PR	09/06/2018	OW	123-45985	Coyote Trails 34S-20-9N	PR
453226	WELL	PR	01/01/2023	OW	123-45986	Coyote Trails 34S-20-8C	PR
453227	WELL	PR	01/01/2023	OW	123-45987	Coyote Trails 34S-20-15N	PR
453228	WELL	PR	02/01/2023	OW	123-45988	Coyote Trails 33S-20-3N	PR
453229	WELL	PR	08/01/2018	OW	123-45989	Coyote Trails 33S-20-7N	PR
453230	WELL	PR	06/01/2019	OW	123-45990	Coyote Trails 34S-20-16N	PR
453231	WELL	PR	08/01/2018	OW	123-45991	Coyote Trails 34S-20-11C	PR
453232	WELL	PR	10/25/2019	OW	123-45992	Coyote Trails 33S-20-4N	PR
453233	WELL	PR	09/08/2018	OW	123-45993	Coyote Trails 34S-20-13N	PR
453234	WELL	PR	09/06/2018	OW	123-45994	Coyote Trails 34S-20-10N	PR
453235	WELL	PR	10/24/2019	OW	123-45995	Coyote Trails 33S-20-5C	PR
453236	WELL	PR	10/24/2019	OW	123-45996	Coyote Trails 33S-20-6N	PR
458185	WELL	PR	10/28/2019	OW	123-48247	Coyote Trails 33W-15-5N	PR
458186	WELL	PR	10/28/2019	OW	123-48248	Coyote Trails 33W-15-7N	PR
458187	WELL	PR	10/28/2019	OW	123-48249	COYOTE TRAILS 33W-15-3N	PR
458188	WELL	PR	10/17/2019	OW	123-48250	Coyote Trails 33W-15-8N	PR

458189	WELL	PR	12/01/2022	OW	123-48251	COYOTE TRAILS 33W-15-2C	PR
458190	WELL	PR	10/28/2019	OW	123-48252	COYOTE TRAILS 33W-15-10C	PR
458191	WELL	PR	10/28/2019	OW	123-48253	COYOTE TRAILS 33W-15-9N	PR
458192	WELL	PR	10/14/2019	OW	123-48254	Coyote Trails 33W-15-4N	PR
458193	WELL	PR	10/17/2019	OW	123-48255	Coyote Trails 33W-15-6C	PR
463041	WELL	PR	10/14/2019	OW	123-49911	Coyote Trails 33W-15-1N	PR
463042	WELL	PR	10/28/2019	OW	123-49912	Coyote Trails 33W-15-11N	PR
463043	WELL	PR	10/28/2019	OW	123-49913	Coyote Trails 33S-20-2C	PR
463044	WELL	PR	10/28/2019	OW	123-49914	Coyote Trails 33S-20-1N	PR

General Comment:
[site inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good, twentyseven wells		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	OTHER		
Comment:	entrance, good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	entrance gate		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 20		
Comment:	electric panels		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 14		

Comment: automation panels		Date:
Corrective Action:		Date:
Type: Bradenhead	# 17	
Comment: piped to surface		
Corrective Action:		Date:
Type: Gathering Line	# 3	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 9	
Comment:		
Corrective Action:		Date:
Type: LACT	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 20	
Comment: piped to surface		
Corrective Action:		Date:
Type: Plunger Lift	# 20	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Compressor	# 3	
Comment: air, recovery, sales		
Corrective Action:		Date:
Type: Bird Protectors	# 20	
Comment:		
Corrective Action:		Date:
Type: FWKO	# 6	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 17	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 20	
Comment: electric/automation		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	48 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-45995
123-48250
123-48248
123-45990

AirsID

API Number	AirsID
------------	--------

123-45987
123-45989
123-45993
123-48254
123-49913
123-48255
123-45986
123-45996
123-45991
123-48251
123-45994
123-45985
123-48252
123-45988
123-45992
123-49911
123-49912
123-45983
123-48247
123-48249
123-49914
123-45984
123-48253

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242874 Type: WELL API Number: 123-10665 Status: PA Insp. Status: PA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: Well is P&A Forms 42 Doc#401405961 and 6 S 401562704 are on file

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453223 Type: WELL API Number: 123-45983 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453224 Type: WELL API Number: 123-45984 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453225 Type: WELL API Number: 123-45985 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453226 Type: WELL API Number: 123-45986 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/22/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 47 Fluid Type: WATER AND GAS
End Surf Csg Pressure: 7

Comment: messco unit on braden head

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453227 Type: WELL API Number: 123-45987 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 24 Fluid Type: WATER AND GAS
End Surf Csg Pressure: 0

Comment: messco unit on braden head

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453228 Type: WELL API Number: 123-45988 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453229 Type: WELL API Number: 123-45989 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453230 Type: WELL API Number: 123-45990 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 89 Fluid Type: GAS
End Surf Csg Pressure: 0

Comment: messco unit on braden head

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453231 Type: WELL API Number: 123-45991 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453232 Type: WELL API Number: 123-45992 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453233 Type: WELL API Number: 123-45993 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453234 Type: WELL API Number: 123-45994 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453235 Type: WELL API Number: 123-45995 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453236 Type: WELL API Number: 123-45996 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458185 Type: WELL API Number: 123-48247 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead			
Date of Last Brhd Test: 01/20/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458186	Type: WELL	API Number: 123-48248	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR.....Valves appeared to be open at time of inspection			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 01/20/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458187	Type: WELL	API Number: 123-48249	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR.....Valves appeared to be open at time of inspection			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 01/20/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458188	Type: WELL	API Number: 123-48250	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment: PR.....Valves appeared to be open at time of inspection			
Corrective Action:		Date:	

--	--	--	--

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 19 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458189 Type: WELL API Number: 123-48251 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458190 Type: WELL API Number: 123-48252 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458191 Type: WELL API Number: 123-48253 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458192 Type: WELL API Number: 123-48254 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458193 Type: WELL API Number: 123-48255 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463041 Type: WELL API Number: 123-49911 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463042 Type: WELL API Number: 123-49912 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463043 Type: WELL API Number: 123-49913 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 01/20/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463044 Type: WELL API Number: 123-49914 Status: PR Insp. Status: PR

Producing Well

Comment: PR.....Valves appeared to be open at time of inspection

Corrective Action: _____

Date: _____

BradenHead		
Date of Last Brhd Test: 01/20/2024	Annual Brhd Completed? Yes	
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:
	End Surf Csg Pressure: 0	
Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Audit of scout card and related documents Routine inspection This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection	kesterm	09/16/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301115	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6709668