

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2024

Submitted Date:

09/17/2024

Document Number:

698602331

**FIELD INSPECTION FORM**Loc ID 411773 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301924	WELL	PR	04/24/2010	GW	125-11672	JONES 41-19 1N44W	PR

**General Comment:**

Routine Inspection.

<b>Location</b>				
<b><u>Lease Road:</u></b>				
Type	Access			
comment:	Two track off maintained County Road.			
Corrective Action				Date:
Overall Good: <input type="checkbox"/>				
<b><u>Signs/Marker:</u></b>				
Type	BATTERY			
Comment:	Well sign posted on gas meter shed at well location.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Well sign located at wellhead.			
Corrective Action:				Date:
<b>Emergency Contact Number:</b>				
Comment:	Emergency contact information posted on well sign.			
Corrective Action:				Date: _____
<b><u>Good Housekeeping:</u></b>				
Type	UNUSED EQUIPMENT			
Comment:	Pump Jack drive belt guard noted on ground inside fencing.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b><u>Spills:</u></b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b><u>Fencing/:</u></b>				
Type	OTHER			
Comment:	Stock panel fencing around surface equipment at gas metering location.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Stock panel fencing around surface equipment at well location.			
Corrective Action:				Date:
<b><u>Equipment:</u></b>				
				corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.			

Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Flowline riser at gas meter shed with valve and plug.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump Jack welded steel pipe base.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve open. Casing valve open.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Gas Meter Shed.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 8-1-24. Meter Calibration/Test Log dated 7-25-24. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	301924	Type:	WELL	API Number:	125-11672	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  Electronic Well File reflects last Production/Status reported 7/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	In Process	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.  
  
Recent heavy rains have created starts of erosion rills at meter run which will need attention and possibly additional BMP's to manage stormwater flowing across location and down grade to prevent soil erosion issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698602365	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711436">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6711436</a>