

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 191 From entrance to location



Photo # 192 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 193 Location



Photo # 194 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 195 Location



Photo # 196 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 197 Location



Photo # 198 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 199 Location




Photo # 200 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 201 Location



Photo # 202 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 203 Location



Photo # 204 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 205 Location



Photo # 206 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 207 Location



Photo # 208 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 209 Location



Photo # 210 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 211 Location



Photo # 212 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 213 Location



Photo # 214 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211




Photo # 215 Location



Photo # 216 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 217 Location



Photo # 218 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 219 Unused equipment



Photo # 220 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 221 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 222 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad

Location ID: 422211



Photo # 223 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 224 PRV vent line does not comply with CECMC pressure safety device rules