

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2024

Submitted Date:

09/18/2024

Document Number:

696206238

**FIELD INSPECTION FORM**

Loc ID 323800 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 760 HORIZON DRIVE STE 401  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Bittner, Dawn [Populus]		stephaniebittner@chevron.com	All NW inspections
Olson, Andrew		AndrewOlson@chevron.com	All NW inspections
,		rbucogccinspectionreports@chevron.com	All NW inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210835	WELL	PA	08/08/2014	CBM	045-06593	CHEVRON SHALE 1-25A CHEVRON	RI

**General Comment:**

On 9/17/2024, Western Reclamation Work Lead Trujillo conducted a Final Reclamation inspection at Chevron Usa Inc's CHEVRON SHALE #1-25A CHEVRON location in Garfield County, Colorado.

This inspection is a follow-up to Inspection #696205961 to document compliance with the following compliance issues:  
-1004 Final Reclamation

It was observed that the Location remains out of compliance with 1004 Reclamation requirements.

Refer to the Reclamation section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Inspected Facilities**

Facility ID: 210835 Type: WELL API Number: 045-06593 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Fail \_\_\_\_\_

Comment [Topsoil on Location has not been replaced, is predominantly bare, and has not been protected pursuant to Rule 1002.c.](#)

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control **Fail**

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present In Process Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

**Corrective Action per Inspection #696205961:**

Comply with Rule 1004.a and conduct reclamation on the Location and access road including, but not limited to, recontouring/regrading, replacement of topsoil and revegetation activities. Ensure erosion controls are implemented to stabilize the seeded soil pursuant to Rule 1002.f. Comply with Rule 1004.e and 606.c and perform ongoing weed management; Oil and Gas Locations will be kept free of all Undesirable Plant Species.

Continue to monitor and manage the Location; ongoing stormwater and weed management required until the site receives a passing final reclamation inspection.

Overall Final Reclamation **Fail** Well Release on Active Location  Multi-Well Location

**ECMC Comments**

Comment	User	Date
<p>Form 6(s) #400682542 states well was P&amp;Ad 8/8/2014.</p> <p>Operator submitted Form 4 #401407509 stating "Final Reclamation was complete".</p> <p>Inspection Nos. 692400010 and 696205961 observed that final reclamation of the Location has not been performed in accordance with 1004 Rules:</p> <p>-Location and access road have not been recontoured/regraded, and reclaimed in accordance with Rule 1004.a. Cut and fill slopes remain apparent; topsoil remains bare and stockpiled on the north, west and southeastern ends of the Location, and has not been replaced. Undesirable Plant Species (Mullein) have continued to establish and spread on the Location and access road.</p> <p>Inspections required Operator to comply with 1004 Rules.</p> <p>It was observed in this inspection that work to reclaim the Location in accordance with 1004 Rules has not been performed, and the Location remains out of compliance. Noxious weeds (Mullein) remain evident on the Location, however weed management efforts do appear to have been previously performed; ongoing weed monitoring/management required until Location receives a passing final reclamation inspection.</p> <p>Corrective actions have not been completed, and remain applicable.</p>	trujilloam	09/18/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696206239	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6712479">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6712479</a>