

Inspection Photos
Location Name: Parmlee 3
API # 05-123-14916



Well



Vegetation

Inspection Photos
Location Name: Parmlee 3
API # 05-123-14916



Vegetation



Vegetation

Inspection Photos
Location Name: Parmlee 3
API # 05-123-14916



Tank needs secondary containment



Appears to be leaking

Inspection Photos
Location Name: Parmlee 3
API # 05-123-14916



Appears to be leaking & Stained Soil



Stained Soil