

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/17/2024

Submitted Date:

09/18/2024

Document Number:

708904620

FIELD INSPECTION FORM

Loc ID 335140	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 18 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257366	WELL	PR	08/01/2018	GW	045-07547	FEDERAL RMV 123-17	PR
283969	WELL	PR	03/23/2006	GW	045-12046	FEDERAL RWF 413-17	PR
283970	WELL	PR	09/05/2006	GW	045-12045	FEDERAL RWF 313-17	PR
283971	WELL	PR	03/23/2006	GW	045-12044	FEDERAL RWF 312-17	PR
283972	WELL	PR	11/03/2006	GW	045-12048	FEDERAL RMV 168-17	PR
283973	WELL	PR	03/23/2006	GW	045-12047	FEDERAL RWF 513-17	PR

General Comment:**CECMC Inspection Report Summary**

On 09/17/2024 at approximately 14:11 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RMV 123-17 Pad.
 Location # 335140 in Garfield County Colorado.
 Location is within High Priority/Density Habitat areas.
 Location is approximately 119 yards from a creek/drainage that contributes to the Colorado River.
 While there, I observed normal production operations.

This is a summary of inspection report.

Shared facilities with the FEDERAL RMV 132-18 pad location # 335412

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Some wellhead signs weathered & cracking but still legible at this time		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:	RWF 312-17 & RMV 123-17 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible. Remaining 4 wells have Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Marked		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	257366	Type:	WELL	API Number: 045-07547 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283969	Type:	WELL	API Number: 045-12046 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283970	Type:	WELL	API Number: 045-12045 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283971	Type:	WELL	API Number: 045-12044 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283972	Type:	WELL	API Number: 045-12048 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	283973	Type:	WELL	API Number: 045-12047 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms						
		Gravel				Sparse to none in sections
Gravel						Sparse to none in most areas
Sediment Traps						
		Compaction				Light compaction in some sections
		Ditches				
Compaction						Small amount of light compaction

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Shared facilities with the FEDERAL RMV 132-18 pad location # 335412	smelserw	09/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904621	Inspection 708904620 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6713282
708904622	Inspection 708904620 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6713283