

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2024

Submitted Date:

09/12/2024

Document Number:

701104067

**FIELD INSPECTION FORM**

Loc ID 316696 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 74740  
Name of Operator: RIO MESA RESOURCES INC  
Address: P.O. BOX 984  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone | Email                         | Comment                     |
|--------------------|-------|-------------------------------|-----------------------------|
| Burn, Diana        |       | diana.burn@state.co.us        |                             |
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us |                             |
| Haverkamp, Curtis  |       | curtis.haverkamp@state.co.us  |                             |
| Mike Hayes         |       | hayespetroleum@gmail.com      | Principal agent per records |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 232261      | WELL | TA     | 11/26/2003  |            | 103-40007 | WOOSLEY 3     | EG          |

**General Comment:**

A survey of the Woosley 3 was performed with FLIR camera and RMLD (Remote Methane Leak Detector) as a follow up to an inspection from 5/14/2021 Document Number:701500762. Due to the light breeze no plume images were captured by the FLIR camera. The RMLD picked up methane PEAK readings as high as 7335 PPMM during lulls in the breeze.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |  |                  |
|--------------------|--|--|------------------|
| Yes/No             | YES  |  |                  |
| Comment:           | Physical inspection of the well indicates that original abandonment was incomplete, hole visible and the presence of methane documented. Abandonment requires complete downhole isolation of a reservoir and eliminating all emission sources.                                       |  |                  |
| Corrective Action: | Well is to be re-entered and replugged to assure that all sources of hydrocarbons are isolated appropriately and potential to emit is eliminated. Form 6 Notice of Intent should be filed by October 15, 2024. It is expected that work is completed and reported by April 15, 2025. |  | Date: 10/15/2024 |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 232261 Type: WELL API Number: 103-40007 Status: TA Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 403918900    | INSPECTION SUBMITTED        | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6703503">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6703503</a> |
| 701104068    | Inspection 701104067 photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6703466">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6703466</a> |