

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2024

Submitted Date:

09/12/2024

Document Number:

695110249

**FIELD INSPECTION FORM**Loc ID 429093 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@fremontpetroleum.comcom	All Inspections
Hart, Tim		thart@fremontpetroleum.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429092	WELL	WO	08/20/2018	LO	043-06216	Pathfinder 1	WO
430103	WELL	PR	06/01/2024	GW	043-06221	Pathfinder 2	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 17: UNUSED EQUIPMENT STORED ON LOCATION (ORANGE 2" POLY PIPE CONNECTED TO PRODUCED WATER TANK IS NOT CONNECTED ON SOUTH END). PHOTO 18: UNUSED EQUIPMENT STORD ON LOCATION (OFFECE AND HEATERS). PHOTO 19: UNUSED EQUIPMENT STORD ON LOCATION (TRUCK, OFFECE AND HEATERS). PHOTO 20: UNUSED EQUIPMENT STORD ON LOCATION (MINING COOLER UNITS AND TANKS). PHOTO 21: UNUSED EQUIPMENT STORD ON LOCATION (MINING COOLER UNITS AND TANKS).		
Corrective Action:	REMOVE ALL UNUSED EQUIPEMENT FROM LOCATION PER RULE 606.	Date:	12/12/2024
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 10: UNUSED EQUIPMENT STORED ON LOCATION (CANVAS TARP). PHOTO 11: UNUSED EQUIPMENT STORED ON LOCATION (POWER CORD). PHOTO 12: UNUSED EQUIPMENT STORED ON LOCATION (EPTY FIBERGLASS BOX AND SOME WATTLE STAKES). PHOTO 13: UNUSED EQUIPMENT STORED ON LOCATION (PALLET OF WATTLES). PHOTO 14: UNUSED EQUIPMENT STORED ON LOCATION (WORK BENCH AND SAW HORSES). PHOTO 15: UNUSED EQUIPMENT STORED ON LOCATION (TRACKOR TIRE, WOOD AND APPEARS TO BE DECK OFF OF A WORKOVER RIG). PHOTO 16: UNUSED EQUIPMENT STORED ON LOCATION (APPEARS TO BE 2 3/8" TUBING).		
Corrective Action:	REMOVE ALL UNUSED EQUIPEMENT FROM LOCATION PER RULE 606. CA DATE 9-18-2024.	Date:	09/18/2024
Type	OTHER		
Comment:	PHOTO 26: AREA OF IMPACTED SOIL APPEARS TO BE OILY WASTE FROM DRAINING SEPARATOR ON GROUND. PHOTO 27: AREA OF IMPACTED SOIL APPEARS TO BE OILY WASTE FROM DRAINING SEPARATOR ON GROUND. PHOTO 27: AREA OF IMPACTED SOIL NEAR LEAKING PUMPJACK MOTOR OR GEAR BOX		
Corrective Action:	REMOVE IMPACTED SOIL AND DISPOSE OF PROPERLY, INCREASE Self-inspection, maintenance, and good housekeeping procedures and schedules.	Date:	10/12/2024
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 22: UNUSED EQUIPMENT ( UNUSED RISERS BY ECD'S). PHOTO 23: UNUSED EQUIPMENT ( UNUSED RISERS BY ECD'S). PHOTO 24: UNUSED EQUIPMENT ( UNUSED RISER NEAR CRUDE OIL TANKS). PHOTO 24: UNUSED EQUIPMENT ( UNUSED RISER NEAR HEATED SEPARATOR).		
Corrective Action:	REMOVE OR MARK UNUSED RISERS PER RULE 606.	Date:	10/12/2024
Type	TRASH		
Comment:	PHOTO 7: TRASH, IT APPEARS TO BE UNED ENGINE OIL IN TWO 5 GAL. BUCKETS NEAR PRIME MOVER. PHOTO 8: TRASH 5 GAL. BUCKETS NEAR WELLHEAD. PHOTO 9: TRASH, SOME KIND OF SCREEN IS DAMAGED.		
Corrective Action:	REMOVE ALL TRASH FROM LOCATION PER RULE 606.	Date:	09/18/2024

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Pump Jack	# 1			corrective date
Comment:				
Corrective Action:				
Date:				
Type: Other	# 3			
Comment: <b>BITCOIN MINING TRAILERS</b>				
Corrective Action:				
Date:				
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:				
Date:				
Type: Deadman # & Marked	# 2			
Comment:				
Corrective Action:				
Date:				
Type: Gas Meter Run	# 1			
Comment: <b>CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.</b>				
Corrective Action:				
Date:				
Type: Bradenhead	# 2			
Comment: <b>BOTH ARE PLUMBED TO SURFACE</b>				
Corrective Action:				
Date:				
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				
Date:				
Type: Ancillary equipment	# 1			
Comment:				
Corrective Action:				
Date:				
Type: Horizontal Heated Separator	# 1			
Comment: <b>PRESSURE RELEAF VALVE WAS POPING OFF ALMOST STEADY</b>				
Corrective Action: <b>REPAIR GAS LEAK, SEE FLIRR VIDEO</b>				
Date: <b>09/13/2024</b>				
Type: Emission Control Device	# 2			
Comment:				
Corrective Action:				
Date:				
Type: Other	# 2			
Comment: <b>GENERATORS</b>				
Corrective Action:				
Date:				

Type: Other	# 1	
Comment:	OFFICE TRAILER	
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		38.329088,-105.178627
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	SHARES BERMS WITH PRODUCED WATER TANKS.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities										
Facility ID:	429092	Type:	WELL	API Number:	043-06216	Status:	WO	Insp. Status:	WO	
Workover										
Comment:		WELL IS WAITING ON COMPLETION								
Corrective Action:								Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	430103	Type:	WELL	API Number:	043-06221	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		PR								
Corrective Action:								Date:		
BradenHead										
Date of Last Brhd Test:		07/20/2023		Annual Brhd Completed?						
Last Brhd Test Results		Initial Surf Csg Pressure:		29		Fluid Type:		VAPOR		
		End Surf Csg Pressure:		0						
Comment:		BRHD TEST PAST DUE SUBMIT REPORTS.								
Corrective Action:								Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403919910	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705722">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705722</a>
695110250	FLIR VIDEO OF GAS LEAK	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705715">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705715</a>
695110251	INSP PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705716">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705716</a>