

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2024

Submitted Date:

09/20/2024

Document Number:

717300046

FIELD INSPECTION FORM

Loc ID 327376 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246793	WELL	SI	07/01/2020	GW	123-14590	HERMAN UPRR 31-31 #1	TA
327376	LOCATION	AC			-	HERMAN UPRR-63N66W 31NWNE	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos Uploaded](#)

Inspected Facilities

Facility ID: 246793 Type: WELL API Number: 123-14590 Status: SI Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 327376 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well (Herman UPRR 31-31 1) is Temporarily Abandoned; On location flowline disconnected/ isolated (air gap) from wellhead and inlet to HHS. Equipment/ flowline valves OOSLAT. No Oxy personnel on location at time of inspection.	maclarej	09/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300049	TA wellhead; Signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715670
717300050	Flowline risers at HHS; OOSLAT	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715672