

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2024

Submitted Date:

09/10/2024

Document Number:

716900014

FIELD INSPECTION FORMLoc ID 319876 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------------|-----------------------------|
| Behrens, Vic | 303-810-6382 | behrens@netecin.net | Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 201697 | WELL | SI | 01/01/2019 | GW | 001-07100 | GREENEMEIER 9-30 (OWP) | SI |

General Comment:

| Location | | | | |
|--|--------------------------------|--------|--|------------------|
| Lease Road: | | | | |
| Type | | | | |
| comment: | | | | |
| Corrective ActionL | | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weeds uncontrolled inside berm | | | |
| Corrective Action: | Comply with Rule 606 | | | Date: 09/17/2024 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | PUMP JACK | | | |
| Comment: | Cattle Fence | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Pump Jack | # 1 | | | corrective date |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Vertical Heated Separator | # 2 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bird Protectors | # 2 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | | |

| | | | |
|--------------------|----------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 39.933499,-104.586493 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|------------------------|---------------------|---------------------|------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Inadequate |
| Comment: | Berms are in disrepair | | | |
| Corrective Action: | Comply with Rule 603 o | | | Date: 09/24/2024 |

Wells Served By Facilities Above**AirsID**

| | | |
|------------|------------|--------|
| API Number | API Number | AirsID |
| 001-07100 | | |

Venting:

| | | |
|--------------------|-----|-------|
| Yes/No | YES | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 201697

Type: WELL

API Number: 001-07100

Status: SI

Insp. Status: SI

Producing Well

Comment:

Corrective Action:

Date:

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---------|-------|------------|
| | huckk | 09/10/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 716900015 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717484 |