

Inspection Photos

September 18th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326146

Inspection Document #: 714001237

La Plata County, CO

Township: SWSE 25 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Burkett 2-25
Location ID: 326146

9/18/24
+37.269708,-107.691714
147° SE




Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Huber Burkett 2-25
Location ID: 326146



Photo 2. View of flowering Musk thistle observed in the southern interim reclamation areas (left) and Canada thistle observed along the base of the cut slope (right).

Inspection Photos
Location Name: Huber Burkett 2-25
Location ID: 326146



Photo 3. View of the northern interim reclamation area facing north.

Inspection Photos
Location Name: Huber Burkett 2-25
Location ID: 326146



Photo 4. Reference area comprised of Gambel oak, Pine and Poa secunda.