

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2024

Submitted Date:

09/18/2024

Document Number:

708904609

FIELD INSPECTION FORM

Loc ID: 422211 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 86 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422222	WELL	PR	03/14/2019	GW	045-20523	Clough NR 523-3	PR
422248	WELL	PR	09/30/2013	GW	045-20525	Clough NR 422-3	PR
454633	WELL	PR	11/14/2018	GW	045-23900	CLOUGH NR 411-3	PR
454634	WELL	PR	08/01/2022	GW	045-23901	CLOUGH NR 14-3	PR
454635	WELL	PR	02/19/2019	GW	045-23902	CLOUGH NR 44-3	PR
454636	WELL	PR	02/19/2019	GW	045-23903	CLOUGH NR 311-3	PR
454637	WELL	PR	08/01/2022	GW	045-23904	CLOUGH NR 22-3	PR
454638	WELL	PR	11/19/2018	GW	045-23905	CLOUGH NR 322-3	PR
454639	WELL	PR	08/01/2022	GW	045-23906	CLOUGH NR 611-3	PR
454640	WELL	PR	02/05/2019	GW	045-23907	CLOUGH NR 413-3	PR
454641	WELL	PR	02/05/2019	GW	045-23908	CLOUGH NR 34-3	PR
454642	WELL	PR	03/07/2019	GW	045-23909	CLOUGH NR 334-3	PR
454643	WELL	PR	02/05/2019	GW	045-23910	CLOUGH NR 343-3	PR
454644	WELL	PR	03/19/2019	GW	045-23911	CLOUGH NR 414-3	PR
454645	WELL	PR	01/15/2019	GW	045-23912	CLOUGH NR 43-3	PR
454646	WELL	PR	03/07/2019	GW	045-23913	CLOUGH NR 434-3	PR
454647	WELL	PR	11/14/2018	GW	045-23914	CLOUGH NR 511-3	PR
454648	WELL	PR	03/19/2019	GW	045-23915	CLOUGH NR 314-3	PR
454649	WELL	PR	01/15/2019	GW	045-23916	CLOUGH NR 23-3	PR
454650	WELL	PR	02/19/2019	GW	045-23917	CLOUGH NR 344-3	PR

454651	WELL	PR	01/15/2019	GW	045-23918	CLOUGH NR 323-3	PR
454652	WELL	PR	02/05/2019	GW	045-23919	CLOUGH NR 443-3	PR
454653	WELL	PR	02/05/2019	GW	045-23920	CLOUGH NR 313-3	PR
454654	WELL	PR	08/01/2022	GW	045-23921	CLOUGH NR 12-3	PR
454655	WELL	PR	03/07/2019	GW	045-23922	CLOUGH NR 312-3	PR
454656	WELL	PR	11/14/2018	GW	045-23923	CLOUGH NR 11-3	PR
454657	WELL	PR	01/15/2019	GW	045-23924	CLOUGH NR 13-3	PR
454664	WELL	PR	03/19/2019	GW	045-23925	CLOUGH RWF 21-10	PR
454665	WELL	PR	03/19/2019	GW	045-23926	CLOUGH RWF 421-10	PR
479163	WELL	PR	09/06/2022	OW	045-24462	FEDERAL NR 43-4	PR
479164	WELL	PR	11/01/2022	OW	045-24463	FEDERAL NR 544-36	PR
479165	WELL	PR	09/01/2022	GW	045-24464	FEDERAL NR 542-3	PR
479166	WELL	PR	11/15/2022	GW	045-24465	FEDERAL NR 432-4	PR
479167	WELL	PR	11/15/2022	OW	045-24466	FEDERAL NR 532-4	PR
479168	WELL	PR	10/25/2022	OW	045-24467	FEDERAL NR 33-4	PR
479170	WELL	PR	09/06/2022	OW	045-24469	FEDERAL NR 543-4	PR
479171	WELL	PR	09/08/2022	OW	045-24470	FEDERAL NR 541-3	PR
479172	WELL	PR	09/07/2022	OW	045-24471	FEDERAL NR 433-4	PR
479173	WELL	PR	10/25/2022	OW	045-24472	FEDERAL NR 331-3	PR
479174	WELL	PR	09/07/2022	OW	045-24473	FEDERAL NR 431-3	PR
479175	WELL	PR	09/20/2022	OW	045-24474	FEDERAL NR 442-3	PR
479176	WELL	PR	10/25/2022	OW	045-24475	FEDERAL NR 333-4	PR
479177	WELL	PR	09/06/2022	OW	045-24476	FEDERAL NR 443-4	PR
479178	WELL	PR	10/25/2022	OW	045-24477	FEDERAL NR 42-3	PR
479179	WELL	PR	11/15/2022	GW	045-24478	FEDERAL NR 444-36	PR
479180	WELL	PR	09/08/2022	OW	045-24479	FEDERAL NR 441-3	PR
479181	WELL	PR	09/06/2022	OW	045-24480	FEDERAL NR 343-4	PR
479182	WELL	PR	11/15/2022	GW	045-24481	FEDERAL NR 32-4	PR
479183	WELL	PR	11/15/2022	GW	045-24482	FEDERAL NR 344-36	PR
479184	WELL	PR	09/07/2022	OW	045-24483	FEDERAL NR 533-4	PR

General Comment:**CECMC Inspection Report Summary**

On 09/12/2024 at approximately 11:42 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Clough NR 23-3 Pad. Location # 422211 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - 3 Rupture disc vent lines & 1 PRV vent line do not comply with CECMC pressure safety device rules with a CA date of 09/25/2024
2. Housekeeping - Unused equipment on location with a CA date of 10/18/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.		Date: 10/18/2024
Type	OTHER		
Comment:	Small amount of staining near multiple wellheads		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heater Treater	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 20		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Qnergy air compressor		
Corrective Action:		Date:	
Type: Bradenhead	# 20		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Qnergy nat gas generator		
Corrective Action:		Date:	
Type: Other	# 4		
Comment:	3 Rupture disc vent lines do not comply with CECMC pressure safety device rules 1 PRV vent line does not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	09/25/2024
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 11		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:			Date:
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 13		
Comment:	Chemical tanks 1 chemical is unused equipment - please refer to Housekeeping for CA		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Thermoelectric generators		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Sand trap		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:	All wells on plunger lift		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment: Tank not equipped with telemetry					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	HEATED STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent			
Comment:		Centralized containment			
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLs	STEEL AST		
Comment:		Tanks equipped with telemetry			
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:		Centralized containment			
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	422222	Type:	WELL	API Number:	045-20523	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	422248	Type:	WELL	API Number:	045-20525	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454633	Type:	WELL	API Number:	045-23900	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454634	Type:	WELL	API Number:	045-23901	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454635	Type:	WELL	API Number:	045-23902	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454636	Type:	WELL	API Number:	045-23903	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454637	Type:	WELL	API Number:	045-23904	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454638	Type:	WELL	API Number:	045-23905	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454639 Type: WELL API Number: 045-23906 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454640 Type: WELL API Number: 045-23907 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454641 Type: WELL API Number: 045-23908 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454642 Type: WELL API Number: 045-23909 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454643 Type: WELL API Number: 045-23910 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454644 Type: WELL API Number: 045-23911 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454645 Type: WELL API Number: 045-23912 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	454646	Type:	WELL
API Number:	045-23913	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	454647	Type:	WELL
API Number:	045-23914	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	454648	Type:	WELL
API Number:	045-23915	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	454649	Type:	WELL
API Number:	045-23916	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	454650	Type:	WELL
API Number:	045-23917	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	454651	Type:	WELL
API Number:	045-23918	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	454652	Type:	WELL
API Number:	045-23919	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID: 454653 Type: WELL API Number: 045-23920 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454654 Type: WELL API Number: 045-23921 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454655 Type: WELL API Number: 045-23922 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454656 Type: WELL API Number: 045-23923 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454657 Type: WELL API Number: 045-23924 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454664 Type: WELL API Number: 045-23925 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454665 Type: WELL API Number: 045-23926 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 479163 Type: WELL API Number: 045-24462 Status: PR Insp. Status: PR

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479164	Type:	WELL	API Number:	045-24463	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479165	Type:	WELL	API Number:	045-24464	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479166	Type:	WELL	API Number:	045-24465	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479167	Type:	WELL	API Number:	045-24466	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479168	Type:	WELL	API Number:	045-24467	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479170	Type:	WELL	API Number:	045-24469	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479171	Type:	WELL	API Number:	045-24470	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479172	Type:	WELL	API Number:	045-24471	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger lift
Corrective Action:	
Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479173	Type:	WELL	API Number:	045-24472	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger lift
Corrective Action:	
Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479174	Type:	WELL	API Number:	045-24473	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger lift
Corrective Action:	
Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479175	Type:	WELL	API Number:	045-24474	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle Well

Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder:	
Comment:	Shut In			
Corrective Action:		Date:		

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479176	Type:	WELL	API Number:	045-24475	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger lift
Corrective Action:	
Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479177	Type:	WELL	API Number:	045-24476	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger lift
Corrective Action:	
Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	479178	Type:	WELL	API Number:	045-24477	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing, well on plunger lift
Corrective Action:	
Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	479179	Type:	WELL
API Number:	045-24478	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	479180	Type:	WELL
API Number:	045-24479	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	479181	Type:	WELL
API Number:	045-24480	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	479182	Type:	WELL
API Number:	045-24481	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	479183	Type:	WELL
API Number:	045-24482	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	479184	Type:	WELL
API Number:	045-24483	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
Compaction						Light compaction in some areas
		Ditches				
Rip Rap						
Waddles						
Ditches						
		Check Dams				
		Waddles				
Hydro Mulch						
		Rip Rap				
				Material Handling And Spill Prevention		Chemical tank containments
Gravel						Sparse to none in areas
		Gravel				Sparse to none in sections
Culverts						
		Culverts				
		Compaction				Light compaction in some sections
Check Dams						

Comment: Some fluid in multiple chemical tank containments, may need maintenance in the near future.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping & Equipment for corrective actions & refer to Stormwater for comments.	smelserw	09/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403926352	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6712486
708904610	Inspection 708904609 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6712480
708904611	Inspection 708904609 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6712481