

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

09/24/2024

Document Number:

713301132

FIELD INSPECTION FORM

Loc ID 449521	Inspector Name: Kester, Michael	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 29 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 69175 Name of Operator: PDC ENERGY INC Address: 1099 18TH STREET SUITE 1500 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, PDC		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449510	WELL	PR	01/01/2024	OW	123-44330	Ottesen LE 09-368HN	PR
449512	WELL	PR	01/01/2024	OW	123-44332	Ottesen LE 09-363HN	PR
449516	WELL	PR	01/01/2024	OW	123-44335	Ottesen LE 06-290HN	PR
449517	WELL	PR	01/01/2024	OW	123-44336	Ottesen LE 09-366HN	PR
449518	WELL	PR	03/01/2024	OW	123-44337	Ottesen LE 06-311HC	PR
449525	WELL	PR	03/01/2024	OW	123-44343	Ottesen LE 09-368HC	PR
449526	WELL	PR	01/01/2024	OW	123-44344	Ottesen LE 09-365HN	PR
449527	WELL	PR	01/01/2024	OW	123-44345	Ottesen LE 06-311HN	PR
449529	WELL	PR	01/01/2024	OW	123-44347	Ottesen LE 06-351HN	PR
449533	WELL	PR	01/01/2024	OW	123-44351	Ottesen LE 09-365HC	PR
449537	WELL	PR	01/01/2024	OW	123-44355	Ottesen LE 06-370HC	PR
449539	WELL	PR	01/01/2024	OW	123-44357	Ottesen LE 06-290HNX	PR
449540	WELL	WO	08/01/2023	LO	123-44358	Ottesen Federal 12N	WO
449546	WELL	PR	01/01/2024	OW	123-44364	Ottesen LE 09-366HNX	PR
449550	WELL	PR	01/01/2024	OW	123-44368	Ottesen LE 09-362HC	PR
458240	WELL	PR	01/01/2024	OW	123-48287	Ottesen LE 06-351HNX	PR
458241	WELL	PR	01/01/2024	OW	123-48288	Ottesen LE 06-370HN	PR

General Comment:

site and faility inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	
Type	OTHER		
Comment:	entrance good		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 5		

Comment:		4 vapor recovery, 1 injection		Date:	
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 7				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 13				
Comment:				Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 19				
Comment:		electric/automatiom panels		Date:	
Corrective Action:				Date:	
Type: FWKO	# 12				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 5				
Comment:				Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: VRU	# 4				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bradenhead	#				
Comment:		piped to surface 49 wells		Date:	
Corrective Action:				Date:	
Type: Pig Station	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	

Other (Capacity) 533 Bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	OTHER	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity) 533 Bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	shared with crude tanks				
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
123-44330
123-44335
123-44287
123-44336
123-44351
123-44357
123-44345
123-44364
123-44368
123-44337
123-44332
123-44347
123-44356
123-44344
123-44343
123-44288

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 449510 Type: WELL API Number: 123-44330 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449512 Type: WELL API Number: 123-44332 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449516 Type: WELL API Number: 123-44335 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449517 Type: WELL API Number: 123-44336 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead			
Date of Last Brhd Test: 12/11/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449518	Type: WELL	API Number: 123-44337	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR, Valves appeared to be open at time of inspection	
Corrective Action:	Date:

BradenHead			
Date of Last Brhd Test: 12/06/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449525	Type: WELL	API Number: 123-44343	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR, Valves appeared to be open at time of inspection	
Corrective Action:	Date:

BradenHead			
Date of Last Brhd Test: 12/11/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449526	Type: WELL	API Number: 123-44344	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: PR, Valves appeared to be open at time of inspection	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 12/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449527 Type: WELL API Number: 123-44345 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449529 Type: WELL API Number: 123-44347 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449533 Type: WELL API Number: 123-44351 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449537 Type: WELL API Number: 123-44355 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449539 Type: WELL API Number: 123-44357 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449540 Type: WELL API Number: 123-44358 Status: WO Insp. Status: WO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449546 Type: WELL API Number: 123-44364 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449550 Type: WELL API Number: 123-44368 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458240 Type: WELL API Number: 123-48287 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type: GAS
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 458241 Type: WELL API Number: 123-48288 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead		
Date of Last Brhd Test:	12/06/2023	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:
	End Surf Csg Pressure: 0	
Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Audit of scout card and related documents Routine inspection This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection	kesterm	09/24/2024
	kesterm	09/24/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301133	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6720208