

Inspection Photos

API: 071-06814

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing southwest toward the access road where erosion is occurring.



Inspection Photos



Photo 1. Facing southwest toward the wellsite.



Inspection Photos



Photo 3. Facing north toward the access road. Stormwater needs to be diverted off the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06814 | Date: 9/23/2024