

Inspection Photos

API: 071-06819

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. This stormwater diversion was cleaned out. The disturbed soils need to be seeded for stabilization.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing back down the road at the wellsite. The road has been graded but no stormwater controls were installed. E.G. gravel, check dams, ect.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06819 | Date: 9/23/2024

Inspection Photos



Photo 3. Facing toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06819 | Date: 9/23/2024