

Inspection Photos

API: 099-06138

Operator: OXY USA INC

Inspection Date: 9/24/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the former access road at Lat/Long:37.87672,-102.72188. This area of the road has eroded and needs to be repaired and reclaimed.



Inspection Photos



Photo 2. Facing west at the location. There are two pipe risers that remain at the location shown at red arrows. Vegetation has not re-established near the risers.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06138 | Date: 9/24/2024

Inspection Photos



Photo 3. Facing east at the location. There are two pipe risers that remain at the location shown at red arrows. Vegetation has not re-established near the risers.



Inspection Photos



Photo 4. Facing northeast. Perennial vegetation has established throughout most of the location.



Inspection Photos



Photo 5. Another pipe riser associated with the well site was found at Lat/Long:37.87789,-102.71800. All equipment/risers need to be removed.

