

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2024

Submitted Date:

09/25/2024

Document Number:

717000055

FIELD INSPECTION FORMLoc ID 449925 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449927	WELL	PR	07/01/2023	OW	001-10011	ALMA WEST 26W-20-01	PR
449929	WELL	PR	02/01/2023	OW	001-10013	ALMA WEST 35W-20-06	PR
449930	WELL	PR	08/01/2023	OW	001-10014	ALMA WEST 26W-20-02	PR
449934	WELL	PR	02/01/2023	OW	001-10018	ALMA WEST 35W-20-04	PR
449935	WELL	PR	07/01/2023	OW	001-10019	ALMA WEST 35W-20-11	PR
449936	WELL	PR	09/01/2023	OW	001-10020	ALMA 1S-66-2524 19NH	PR
449942	WELL	PR	07/01/2023	OW	001-10026	ALMA WEST 35W-20-05	PR
449943	WELL	PR	07/01/2023	OW	001-10027	ALMA 1S-66-2524 20CDH	PR

General Comment:[Routine Inspection](#)

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:		<div>Adequate</div>			
Corrective Action:		<div></div>			Date: <div></div>
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:		<div></div>			
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					corrective date
Type: Bird Protectors	# 16				
Comment:					
Corrective Action:					Date:
Type: Horizontal Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 9				
Comment:					
Corrective Action:					Date:
Type: Vertical Separator	# 2				
Comment:					
Corrective Action:					Date:
Type: LACT	# 2				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:					Date:
Type: Emission Control Device	# 3				
Comment:					
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 9				
Comment:					
Corrective Action:					Date:

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	8	400 BBLs	STEEL AST		39.929250,-104.722503	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

AirsID

Wells Served By Facilities Above		API Number	AirsID
API Number			
001-10022			
001-10026			
001-10020			
001-10013			
001-10019			
001-10018			
001-10014			
001-10027			
001-10011			
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 449927	Type: WELL	API Number: 001-10011	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449929	Type: WELL	API Number: 001-10013	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449930	Type: WELL	API Number: 001-10014	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449934	Type: WELL	API Number: 001-10018	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449935	Type: WELL	API Number: 001-10019	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449936	Type: WELL	API Number: 001-10020	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449942	Type: WELL	API Number: 001-10026	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449943	Type: WELL	API Number: 001-10027	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/19/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to the surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

Routine Inspection

finkenbc

09/25/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000056	INSPECTION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721316