

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2024

Submitted Date:

09/19/2024

Document Number:

713400329

FIELD INSPECTION FORM

Loc ID 334539 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Operator Information:
ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
18 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287062	WELL	PR	10/24/2008	GW	077-09151	UTE WATER 22-10	PR
287063	WELL	PR	11/01/2010	GW	077-09150	UTE WATER 22-11	PR
287064	WELL	PR	12/20/2007	GW	077-09149	UTE WATER 22-12	PR
287065	WELL	PR	03/01/2017	GW	077-09148	UTE WATER 22-13	PR
287066	WELL	PR	04/01/2024	GW	077-09147	UTE WATER 22-14	PR
287067	WELL	PR	03/01/2017	GW	077-09146	UTE WATER 22-15	PR
287068	WELL	PR	03/01/2017	GW	077-09145	UTE WATER 27-2	PR
287069	WELL	PR	03/01/2017	GW	077-09144	UTE WATER 27-3	PR

General Comment:

[CECMC Inspection Report Summary](#)

On 9/17/2024 at approximately 14:57, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Ute Water/22-14 Pad at Location ID #334539 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Housekeeping:
1- Loose barbed wire on northeast corner of location/wildlife hazard with a CA date of 9/26/2024

Equipment:
2- Methanol tank hatch is open to wildlife with a CA date 9/26/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	1 condensate tank label is peeling.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/1-800-891-6191		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Loose barbed wire on northeast corner of location/wildlife hazard, refer to photos.		
Corrective Action:	Comply with CECMC wildlife rules.	Date:	09/26/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 8		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	All Bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Methanol tank hatch is open to wildlife/ available for entry by wildlife, refer to photos.		
Corrective Action:	Comply with CECMC wildlife rules.		Date: 09/26/2024
Type: Vertical Heated Separator	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		
Comment:	500 gal				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLS	STEEL AST		
Comment:	Telemetry on 3 tanks.				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	287062	Type:	WELL	API Number:	077-09151	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	287063	Type:	WELL	API Number:	077-09150	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	287064	Type:	WELL	API Number:	077-09149	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	287065	Type:	WELL	API Number:	077-09148	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	287066	Type:	WELL	API Number:	077-09147	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	287067	Type:	WELL	API Number:	077-09146	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	287068	Type:	WELL	API Number:	077-09145	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	287069	Type:	WELL	API Number:	077-09144	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Producing Well

Comment: Producing well.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
Compaction						
		Compaction				
		Berms				
Berms						
Seeding						
Ditches						
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403928583	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6714669
713400331	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6714663