

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 1: Tank Battery Sign

Photo 2: Tank Battery

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 3: Overgrown vegetation

Photo 4: Overgrown vegetation

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 5: Overgrown vegetation

Photo 6: No NFPA placard

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176




Photo 7: No NFPA placard

Photo 8: Overgrown vegetation

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 9: Overgrown vegetation



Photo 10: Overgrown vegetation

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 11: Overgrown vegetation

Photo 12: Wellhead Sign

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 13: Pumpjack



Photo 14: Stained soil

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Energy & Carbon Management Commission
40.11104, -104.88385, 1512.5m, 177°
Sep 26, 2024 10:03:38

Photo 15: Stained soil



Energy & Carbon Management Commission
40.11116, -104.88452, 1511.4m, 245°
Sep 26, 2024 10:35:54

Photo 16: Pilot does not appear to be on