

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2024

Submitted Date:

09/26/2024

Document Number:

707603231

**FIELD INSPECTION FORM**

Loc ID 302303 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297868	WELL	PA	11/25/2019	OW	123-28108	ROTHER 29BU	PA
446871	TANK BATTERY	AC	07/22/2016		-	ROTHER-65N63W 29SESW	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment has been removed.  
Abandoned Battery SE corner GPS coordinates: 40.366201 / -104.464366

Abandoned Centralized Battery formerly served 5 Location IDs  
(302303, 306702, 306703, 306704, 306705).  
(Well(s): 5: Plugged & Abandoned | PA).

Abandoned Centralized Battery formerly served 1 Tank Battery Facility ID  
(446871).

**Inspected Facilities**

Facility ID: 297868 Type: WELL API Number: 123-28108 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 446871 Type: TANK API Number: - Status: AC Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 09/26/2024 at approximately 13:50 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: PDC ENERGY INC                      Facility Name: ROTHE-65N63W/29SESW                      Facility ID: 446871                      Location Name: ROTHE-65N63W/29SESW                      Location ID: 302303                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this Field Inspection Report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Abandoned. ALL equipment has been removed.                      Abandoned Battery SE corner GPS coordinates: 40.366201 / -104.464366</p> <p>WELL STATUS COMMENT:                      Plugged &amp; Abandoned   PA.                      Form 6-SRA on file. Plugging, cut/cap date: 11/25/2019. Approved.                      Plugged &amp; Abandoned   PA well GPS coordinates: 40.366580 / -104.464640</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	09/26/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603232	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723630">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723630</a>