

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2024

Submitted Date:

09/18/2024

Document Number:

711901281

FIELD INSPECTION FORMLoc ID 317087 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 95800

Name of Operator: WESTGATE OIL CO

Address: 403 N MYRTLE

City: EUREKA State: KS Zip: 67045

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hough, Kevin		houghkevin@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236054	WELL	PR	07/01/2018	OW	121-08544	DANIELS 1	PR

General Comment:

ROUTINE FIR 2024

Location

Lease Road:			
Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:	REMOVE TUBING LAYING ON GROUND: SEE ATTACHED PHOTO		Date: 09/30/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: NONE

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	236054	Type:	WELL	API Number:	121-08544	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	OW								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment						User		Date	
REMOVE TUBING LAYING ON GROUND						schureky		09/18/2024	
Attached Documents									
You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:									
Document Num	Description				URL				
403928927	INSPECTION SUBMITTED				https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715181				
711901282	REMOVE TUBING				https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6715175				