

Inspection Photos
Operator: Dover Atwood/Envex Baca
Location Name: Gibson, Leslie 2-19 API: 009-06072



1. Pumping unit and water tank on north side of wellhead



2. Water tank has no berms. Meter run on south side of wellhead

Inspection Photos
Operator: Dover Atwood/Envex Baca
Location Name: Gibson, Leslie 2-19 API: 009-06072



3. Wellhead and water leg. Fencing laying on the ground



4. Meter run door laying on the ground. Lease sign isn't legible