

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2024

Submitted Date:

09/27/2024

Document Number:

713301144**FIELD INSPECTION FORM**Loc ID 450677 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450672	WELL	PR	08/01/2018	OW	123-44864	COCHRAN 26C-2HZ	PR
450673	WELL	PR	09/06/2018	OW	123-44865	COCHRAN 1N-2HZ	PR
450674	WELL	PR	09/04/2018	OW	123-44866	COCHRAN 27N1-2HZ	PR
450675	WELL	PR	10/01/2022	OW	123-44867	COCHRAN 28N1-2HZ	PR
450676	WELL	PR	08/01/2022	OW	123-44868	COCHRAN 2C-2HZ	PR
450678	WELL	PR	09/04/2018	OW	123-44869	COCHRAN 2N-2HZ	PR
450679	WELL	PR	09/03/2018	OW	123-44870	COCHRAN 28N2-2HZ	PR
450680	WELL	PR	01/01/2022	OW	123-44871	COCHRAN 27N2-2HZ	PR
450681	WELL	PR	08/01/2018	OW	123-44872	COCHRAN 27C-2HZ	PR

General Comment:[well pad site inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	good, nine wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 9		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 12		
Comment:	electric/automation panels		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 450672 Type: WELL API Number: 123-44864 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450673 Type: WELL API Number: 123-44865 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/13/2024 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450674 Type: WELL API Number: 123-44866 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450675 Type: WELL API Number: 123-44867 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:		Date:	
<u>BradenHead</u>			
Date of Last Brhd Test: 08/15/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results Initial Surf Csg Pressure: 1		Fluid Type: None	
End Surf Csg Pressure: --			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450676 Type: WELL API Number: 123-44868 Status: PR Insp. Status: PR

<u>Producing Well</u>	
Comment: PR, Valves appeared to be open at time of inspection	
Corrective Action:	Date:

<u>BradenHead</u>			
Date of Last Brhd Test: 08/15/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results Initial Surf Csg Pressure: 1		Fluid Type: None	
End Surf Csg Pressure: --			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450678 Type: WELL API Number: 123-44869 Status: PR Insp. Status: PR

<u>Producing Well</u>	
Comment: PR, Valves appeared to be open at time of inspection	
Corrective Action:	Date:

<u>BradenHead</u>			
Date of Last Brhd Test: 08/15/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results Initial Surf Csg Pressure: 5		Fluid Type: None	
End Surf Csg Pressure: --			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450679 Type: WELL API Number: 123-44870 Status: PR Insp. Status: PR

<u>Producing Well</u>	
Comment: PR, Valves appeared to be open at time of inspection	
Corrective Action:	Date:

BradenHead

Date of Last Brhd Test: 08/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450680 Type: WELL API Number: 123-44871 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 08/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 450681 Type: WELL API Number: 123-44872 Status: PR Insp. Status: PR

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 08/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Audit of scout card and related documents Routine inspection	kestern	09/27/2024
This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301145	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6725653