

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2024

Submitted Date:

09/23/2024

Document Number:

715200980

FIELD INSPECTION FORMLoc ID 321046 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|------------------------|---------|
| Kelly, George | | envexbaca@aol.com | |
| Levengood, John | (330) 809-0630 | jlevengood07@gmail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 205855 | WELL | PR | 07/01/2019 | GW | 009-06270 | HANCOCK M 1 | PR |

General Comment:

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Location

| | | | |
|--------------------|-------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through farm ground | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Stickers on tank are peeling off and need replaced | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 10/23/2024 |
| Type | WELLHEAD | | |
| Comment: | Lease sign by water tank is faded | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 10/23/2024 |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | Maintain weeds around welhead and cathodic rectifier | | |
| Corrective Action: | Comply with Rule 606 | Date: | 10/23/2024 |

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------------------------|-------|--|
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | Pipe cage around cathodic rectifier | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | American unit. Horsehead removed at time of inspection | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run is 100' to the west of wellhead. Meter shed is leaning and needs to be fixed | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Solar powered cathodic rectifier and gas scrubber | | |

| | | | |
|--------------------|------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Arrow gas engine | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|----------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 100 BBLs | Open Top | | 37.362420,-102.238500 | |
| Comment: | Fiberglass open top water tank. Tank is empty at time of inspection | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | | |
|--------------------|--|---------------------|---------------------|-------------|------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | Berms around tank need maintenance | | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 603.o. | | | | Date: 10/23/2024 |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|---|-------|------|-------------|-----------|---------|----|---------------|------------|
| Facility ID: | 205855 | Type: | WELL | API Number: | 009-06270 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing gas production. Last reported production was 11/1/23. Casing valve is unable to close (see photo #4) | | | | | | | | |
| Corrective Action: | Submit reports as per Rule 207. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | | | | | | | Date: | 10/23/2024 |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403931111 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717490 |
| 715200990 | Location photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6717481 |