

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2024

Submitted Date:

09/30/2024

Document Number:

714201727

FIELD INSPECTION FORM

Loc ID 332884 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240492	WELL	SI	06/01/2024	OW	123-08280	CLEVELAND 2	TA

General Comment:

[This is an audit of CLEVELAND #2 scout card and related documents followed by a field inspection.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused/disconnected equipment. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	05/02/2024
Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	10/30/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240492 Type: WELL API Number: 123-08280 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; equipment appears to be disconnected.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/03/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: 40.111000 Long: -104.902800

Wind: Gusts Speed: 17 (mph) Direction From: NE Weather: Clear Temperature: 75 (F)

Assisting Staff Brittani Santistevan Camera #: _____

Visible Smoke Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
1327	PM	1329	PM	Wellhead(s)

Comment: The wellhead appears to not be omitting emissions into the atmosphere. See attached video.

Corrective Action: Date: _____

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground. On Monday, September 30, 2024 at approximately 1315, I, Inspector Brittani Santistevan, conducted an on-site inspection at CLEVELAND #2 (KP Kauffman Company, Inc.), at location ID: 332884 in WELD COUNTY, Colorado. While there, I observed a TA wellhead. During this inspection the following possible compliance issues were observed: 1. It appears to be overgrown vegetation on various areas of location. Remove to Comply with Rule 606. (Corrective Action Date: October 30, 2024) See attached photo #1, 3-5. 2. It appears to be disconnected/unused equipment to pumpjack on location. Reconnect or remove from location to comply with Rule 606. (Corrective Action Date: May 2, 2024) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	09/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201728	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728242
714201735	Wellhead Video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6728243