

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2024

Submitted Date:

09/23/2024

Document Number:

717000044

FIELD INSPECTION FORMLoc ID 320154 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Espinosa, Bill		billespinosa30@yahoo.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202844	WELL	TA	08/31/2023	GW	001-08249	CHAMPLIN 248 AMOCO C 8	TA

General Comment:[Routine Inspection](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: ADEQUATE

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds throughout the location.		
Corrective Action:	Rule 606: Weeds (weeds throughout the location). Within the designated setback, weeds per Rule 606. Corrective Action Date 10/11/2024. See attached photo # 1 & 2.	Date:	10/11/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202844

Type: WELL

API Number: 001-08249

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: TA

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>CECMC Inspection Report Summary</div> <div>On Friday September 20th 2024 at approximately 14:37pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection.</div> <div>Operator: RENEGADE OIL & GAS</div> <div>Location name: CHAMPLIN 248 AMOCO C8</div> <div>API #05-001-08249</div> <div>Location ID #: 320158</div> <div>County: Adams</div> <div>While there, I observed a SHUT IN well.</div> <div>During this inspection the following possible compliance issues were observed:</div> <div>Rule 606: Weeds (weeds throughout the location). Within the designated setback, weeds per Rule 606. Corrective Action Date 10/11/2024. See attached photo # 1 & 2.</div> <div>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</div> <div>This is a summary of inspection report.</div>	finkenbc	09/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403933039	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719431
717000045	INSPECTION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719424