

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2024

Submitted Date:

09/24/2024

Document Number:

701104072

**FIELD INSPECTION FORM**

Loc ID: 324377 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Wheeler, Steven		steven.wheeler@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285502	WELL	PR	07/23/2007	GW	045-12464	MOSS NER 413-6	EG

**General Comment:**

Flowline integrity inspection  
Staff Mike Longworth was inspecting unregistered domestic tap that was notified of by Compliance Specialist Smelser, Wayne. Domestic tap was discovered by Scott Ramsey during an inspection on 5/10/2022 doc # 70074178. Corrective action given was to "Provide documentation of domestic tap" by 6/24/2022.  
Resident of the property made contact with Mike Longworth at domestic tap and reached out to her father land owner and TEP employee Brad Moss. Brad meet me out at the domestic tap and discussed the tap and explaining he had believed it to have been registered along with another domestic tap nearby. Brad said he would look into it.



**Inspected Facilities**

Facility ID: 285502 Type: WELL API Number: 045-12464 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403932970	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719339">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719339</a>
701104073	Flowline integrity inspection 701104072 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719337">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6719337</a>