

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2024

Submitted Date:

10/01/2024

Document Number:

708302830

FIELD INSPECTION FORM

Loc ID 334128	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, CAERUS		ecmc.inspections@qb-energy.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277323	WELL	PR	07/01/2024	GW	045-10666	BATTLEMENT MESA 26-42	PR
295394	WELL	PR	11/01/2017	GW	045-15739	BATTLEMENT MESA 26-33D	PR
295395	WELL	PR	06/01/2023	GW	045-15740	BATTLEMENT MESA 26-23D	PR
295396	WELL	PR	12/01/2017	GW	045-15741	BATTLEMENT MESA 26-34C	PR
295397	WELL	PR	01/07/2011	GW	045-15742	BATTLEMENT MESA 26-33C	PR
295398	WELL	PR	11/01/2017	GW	045-15743	BATTLEMENT MESA 26-33B	PR
295399	WELL	PR	01/25/2011	GW	045-15744	BATTLEMENT MESA 26-34A	PR
295400	WELL	PR	08/01/2020	GW	045-15745	BATTLEMENT MESA 26-34B	PR
295401	WELL	PR	11/01/2017	GW	045-15746	BATTLEMENT MESA 26-24D	PR
295402	WELL	PR	06/01/2023	GW	045-15747	BATTLEMENT MESA 26-24B	PR
295403	WELL	PR	08/01/2020	GW	045-15748	BATTLEMENT MESA 26-34D	PR
295404	WELL	PR	09/24/2009	GW	045-15749	BATTLEMENT MESA 26-24C	PR

General Comment:

CECMC Inspection Report Summary

On 9/26/2024 at approximately 12:25, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, Battlement Mesa/26N-795 at Location ID #334128 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

1) Damaged barbed wire fencing on east side of location

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Damaged barbed wire fencing along east side of location.		
Corrective Action:	Repair fencing to comply with Rule 602.c.	Date:	10/16/2024
Type	TANK BATTERY		

Comment: Cattle panels			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 12		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Chemical tank			
Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 12		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 277323	Type: WELL	API Number: 045-10666	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 295394	Type: WELL	API Number: 045-15739	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 295395	Type: WELL	API Number: 045-15740	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 295396	Type: WELL	API Number: 045-15741	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 295397	Type: WELL	API Number: 045-15742	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 295398	Type: WELL	API Number: 045-15743	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 295399	Type: WELL	API Number: 045-15744	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 295400	Type: WELL	API Number: 045-15745	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well									
Comment:									
Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295401	Type:	WELL	API Number:	045-15746	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295402	Type:	WELL	API Number:	045-15747	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295403	Type:	WELL	API Number:	045-15748	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295404	Type:	WELL	API Number:	045-15749	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap				
		Check Dams				
		Ditches				
Berms						
Compaction						
		Compaction				
		Gravel				
		Culverts				
		Sediment Traps				
		Drains				
				Material Handling And Spill Prevention		
Gravel						

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302831	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729278