

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2024

Submitted Date:

10/01/2024

Document Number:

708904705

FIELD INSPECTION FORM

Loc ID: 335478
Inspector Name: Smelser, Wayne
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296693	WELL	PR	05/20/2009	GW	045-16101	SAVAGE RWF 411-26	PR
297597	WELL	PR	05/20/2009	GW	045-16886	SAVAGE RMV 149-26	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 09/26/2024 at approximately 14:06 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RWF22-26 Pad.
Location # 335478 in Garfield County Colorado.
Please refer to inspection 708904632 conducted on 09/19/2024, previous corrective actions have been completed.
Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost Site.
Location is approximately 450 yards from Porcupine Creek.
Location is approximately 475 yards from Beaver Creek.
While there, I observed workover rig performing P & A operations on the SAVAGE RMV149-26 well.

This is a summary of inspection report.

This inspection is limited in scope focusing primarily on the SAVAGE RWF 411-26 & SAVAGE RMV 149-26 wells.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Rig sign at intersection of county road & start of lease road		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Wireline truck		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:			Date:
Type: Other	# 6		
Comment:	Fire extinguishers		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:			Date:
Type: Other	# 1		

Comment:	Cement pump truck		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Accumulator		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 296693 Type: WELL API Number: 045-16101 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297597 Type: WELL API Number: 045-16886 Status: PR Insp. Status: PR

Cement

Cement Contractor

Contractor Name: American

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment:

Arrived on location just after crew pumped cement downhole.
Observed rig crew tripping out & wireline then running downhole.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited inspection due to ongoing P & A operations on location](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Limited inspection due to ongoing P & A operations on location	smelserw	10/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904706	Inspection 708904705 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6729724