

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2024

Submitted Date:

09/25/2024

Document Number:

713601448

## FIELD INSPECTION FORM

Loc ID 307766 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

## Operator Information:

ECMC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

## Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:

| Contact Name       | Phone                     | Email                         | Comment |
|--------------------|---------------------------|-------------------------------|---------|
| Mattorano, Michael | 575-445-6704/505-652-0416 | mmattorano@wapitienergy.com   |         |
| Madison, Randy     | 575-445-6706/575-420-1120 | rmadison@wapitienergy.com     |         |
| Middlebrook, Sonny | 575-445-6724/575-445-8610 | smiddlebrook@wapitienergy.com |         |

## Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 256741      | WELL | PR     | 02/09/2000  | CBM        | 071-06931 | VPR C 29      | RI          |

## General Comment:

This is a follow up of the previous inspections #713600563, #713601112.  
The previous inspection corrective action has not been completed.

Operator is directed to perform corrective actions outlined on this inspection report immediately.

Reclamation - Storm Water - Pit

Storm Water:

|  |                 |  |                       |               |                          |             |
|--|-----------------|--|-----------------------|---------------|--------------------------|-------------|
| Loc Erosion BMPs   | BMP Maintenance | Lease Road Erosion BMPs  | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment     |
|  |                 |  |                       |               |                          |             |
| Comment:   |                 | There are areas of erosion along the fill and cut slopes that need to be repaired and stabilized. Previous corrective action was not completed |                       |               |                          |             |
| Corrective Action:   |                 | Install or repair required BMPs per Rule 1002.f.(2)  |                       |               |                          | Date: _____ |
| Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT |                 |  |                       |               |                          |             |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403933933    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6720485">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6720485</a> |
| 713601450    | Inspection Photos    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6720474">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6720474</a> |