

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2024

Submitted Date:

10/02/2024

Document Number:

716200787**FIELD INSPECTION FORM**Loc ID 449884 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449881	WELL	PR	07/01/2023	OW	123-44563	NEWBY STATE 30N-34HZ	PR
449882	WELL	PR	05/01/2024	OW	123-44564	NEWBY 1N-33HZ	PR
449883	WELL	PR	05/01/2022	OW	123-44565	NEWBY STATE 26N-33HZ	PR
449885	WELL	PR	06/01/2020	OW	123-44566	NEWBY 27N-33HZ	PR
449886	WELL	PR	07/01/2023	OW	123-44567	NEWBY 28N-33HZ	PR
449887	WELL	PR	04/01/2020	OW	123-44568	NEWBY 2N-33HZ	PR
451358	WELL	PR	04/01/2020	OW	123-45087	NEWBY STATE 37N-4HZ	PR
451359	WELL	PR	10/21/2018	OW	123-45088	NEWBY STATE 16N-4HZ	PR
451360	WELL	PR	04/01/2020	OW	123-45089	NEWBY STATE 15N-4HZ	PR
451361	WELL	PR	10/13/2018	OW	123-45090	NEWBY STATE 34N-3HZ	PR
451362	WELL	PR	04/01/2022	OW	123-45091	NEWBY STATE 36N-4HZ	PR
451363	WELL	PR	10/13/2018	OW	123-45092	NEWBY STATE 38N-4HZ	PR

General Comment:

This is a routine Wellhead audit.
 Location is undergoing transition to gas lift systems.
 Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 449881 Type: WELL API Number: 123-44563 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449882 Type: WELL API Number: 123-44564 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449883 Type: WELL API Number: 123-44565 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449885 Type: WELL API Number: 123-44566 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449886 Type: WELL API Number: 123-44567 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449887 Type: WELL API Number: 123-44568 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

Workover

Comment: AXIS R2721Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451358 Type: WELL API Number: 123-45087 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451359 Type: WELL API Number: 123-45088 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451360 Type: WELL API Number: 123-45089 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451361 Type: WELL API Number: 123-45090 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451362 Type: WELL API Number: 123-45091 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451363 Type: WELL API Number: 123-45092 Status: PR Insp. Status: PR

Idle Well		
Purpose: <input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment: <input type="text" value="SI"/>		
Corrective Action: <input type="text"/>		Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<p>This is a routine Wellhead audit. Location is undergoing transition to gas lift systems. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</p>	carlilec	10/02/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716200788	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6730319

