

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2024

Submitted Date:

10/02/2024

Document Number:

715201022

FIELD INSPECTION FORMLoc ID 324872 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 37230

Name of Operator: HALDE OIL INC

Address: 46321 HWY 24

City: BURLINGTON State: CO Zip: 80807

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Halde, Kerry	719-346-0653	haldeoil@hotmail.com	
Shalberg, Greg		gregshalberg@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213346	WELL	SI	03/01/2024	GW	061-06708	MAYER 12-2 1	SI

General Comment:

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign where the tank used to be		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds across location		
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	SM-Cyclo 160		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on west side of metal shed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber, solar powered cathodic rectifier, telemetry equipment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed on northwest corner of location		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Skid mounted gas powered booster compressor in metal shed		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0	400 BBLs	FIBERGLASS AST		38.609200,-102.544750	
Comment:	Tank on west side of wellhead has been removed from location					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	213346	Type:	WELL	API Number:	061-06708	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Wel is SI at time of inspection. Form 6N (403873917) has been approved								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201033	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6730983