

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2024

Submitted Date:

10/02/2024

Document Number:

715201024

**FIELD INSPECTION FORM**Loc ID 324853 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 37230

Name of Operator: HALDE OIL INC

Address: 46321 HWY 24

City: BURLINGTON State: CO Zip: 80807

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	
Halde, Kerry	719-346-0653	haldeoil@hotmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213222	WELL	SI	05/01/2024	OW	061-06584	JAGEE 1	TA

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by stairs at tanks		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Piping, valves and misc stuff laying around. Well is going to be plugged and debris will need to be removed.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: FWKO	# 1			
Comment:	FWKO on east side of oil tanks			
Corrective Action:			Date:	
Type: Prime Mover	# 0			
Comment:	Removed from location			
Corrective Action:			Date:	
Type: Ancillary equipment	# 0			
Comment:	Removed from location			
Corrective Action:			Date:	
Type: Pump Jack	# 0			
Comment:	Removed from location			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		38.509800,-102.395170

Comment:		Fiberglass open top water tank on east side of location					
Corrective Action:						Date:	

**Paint**

Condition						
Other (Content)						
Other (Capacity)	210bbls					
Other (Type)						

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	300 BBLs	STEEL AST		38.509750,-102.395550		

Comment:		Tanks have load lines removed. Manway covers are removed. Tanks will be removed when well is plugged					
Corrective Action:						Date:	

**Paint**

Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

**Venting:**

Yes/No						
Comment:						
Corrective Action:					Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	213222	Type:	WELL	API Number:	061-06584	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: Well is TA at time of inspection. Form 6N (403874119) has been approved.									
Corrective Action:									
Date:									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201034	wellhead photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6730984">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6730984</a>
715201035	tank battery location	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6730986">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6730986</a>