

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/3/2024



Location Entrance – Photo #03866



Wellheads – Photo #03880

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/3/2024



Separators – Photo #03877



Open-Ended Load Line – Photo #03867



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/3/2024



Open-Ended Load Line – Photo #03868



Open-Ended Load Line – Photo #03869

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/3/2024



Open-Ended Vent Line – Photo #03870



Open-Ended Vent Lines – Photo #03871

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/3/2024



Rill Erosion on Access Road into Location – Photo #03865



Rill Erosion on Access Road to Wellheads – Photo #03878

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/34-4

Location ID: 334896

Date: 10/3/2024



**Rill Erosion from Access Road Transporting Sediment Offsite
– Photo #03879**