

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2024

Submitted Date:

10/02/2024

Document Number:

699506413

**FIELD INSPECTION FORM**Loc ID 449176 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449175	WELL	SI	03/01/2024	OW	001-10003	King 3-65 28-29 3AH	SI
458413	WELL	SI	03/01/2024	OW	001-10224	King 3-65 28-29 3DH	SI
458414	WELL	SI	03/01/2024	OW	001-10225	King 3-65 28-29 3CH	SI
458415	WELL	SI	03/01/2024	OW	001-10226	King 3-65 28-29 3BH	SI
486009	WELL	WO	06/01/2024		001-10557	Bear 3-65 22-23 4BH	WO
486034	WELL	WO	06/01/2024		001-10558	Florida 3-65 27-26 1AH	WO
486035	WELL	WO	06/01/2024		001-10559	Florida 3-65 27-26 1BH	WO
486036	WELL	WO	06/01/2024		001-10560	Florida 3-65 27-26 2AH	WO
486037	WELL	WO	06/01/2024		001-10561	Florida 3-65 27-26 4AH	WO
486038	WELL	WO	06/01/2024		001-10562	Florida 3-65 27-26 4BH	WO
486039	WELL	WO	06/01/2024		001-10563	King 3-65 28-29- 1AH	WO
486040	WELL	WO	06/01/2024		001-10564	King 3-65 28-29 1BH	WO
486041	WELL	WO	06/01/2024		001-10565	King 3-65 28-29 2AH	WO
486042	WELL	WO	06/01/2024		001-10566	King 3-65 28-29 2BH	WO
486043	WELL	WO	06/01/2024		001-10567	King 3-65 28-29 4AH	WO
486044	WELL	WO	06/01/2024		001-10568	King 3-65 28-29 4BH	WO
487621	SPILL OR RELEASE	CL	08/14/2024		-	King 3-65 28-29	CL

**General Comment:**

There have been no changes to equipment on location since previous inspection.

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:		<input type="text"/>			
Corrective Action:		<input type="text"/>		Date: <input type="text"/>	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:		<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>			Date:	<input type="text"/>
Flaring:					
Type	<input type="text"/>				
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>			Date:	<input type="text"/>

Inspected Facilities					
Facility ID: 449175	Type: WELL	API Number: 001-10003	Status: SI	Insp. Status: SI	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 458413	Type: WELL	API Number: 001-10224	Status: SI	Insp. Status: SI	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 458414	Type: WELL	API Number: 001-10225	Status: SI	Insp. Status: SI	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 458415	Type: WELL	API Number: 001-10226	Status: SI	Insp. Status: SI	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486009	Type: WELL	API Number: 001-10557	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486034	Type: WELL	API Number: 001-10558	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486035	Type: WELL	API Number: 001-10559	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486036	Type: WELL	API Number: 001-10560	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486037	Type: WELL	API Number: 001-10561	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486038	Type: WELL	API Number: 001-10562	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486039	Type: WELL	API Number: 001-10563	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486040	Type: WELL	API Number: 001-10564	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486041	Type: WELL	API Number: 001-10565	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486042	Type: WELL	API Number: 001-10566	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486043	Type: WELL	API Number: 001-10567	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 486044	Type: WELL	API Number: 001-10568	Status: WO	Insp. Status: WO	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					

Facility ID:	487621	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	CL
--------------	--------	-------	----------	-------------	---	---------	----	---------------	----

Workover

Comment: At time of inspection there were multiple ops on location. Location production equipment was being installed. Stand alone snubbing unit was in process of moving other to next well to install tubing. Wireline operations were on the adjacent well, and coil tubing was cleaning out the Florida 1BH.

Corrective Action:	
--------------------	--

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, clear.	medinaj	10/02/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506414	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6733676">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6733676</a>