

Inspection Photos

API: 061-06403

Operator: STRACHAN EXPLORATION INC

Inspection Date: 10/3/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the offsite tank battery location. The fence is not adequate to prevent livestock entry and there is no gate at the red arrow.



Inspection Photos



Photo 2. Facing southwest at the wellsite.



Inspection Photos



Photo 3. Facing toward the tank. The berm around the tank has been rebuilt. The sides of the berm are not compacted.



Inspection Photos



Photo 4. A new well sign was installed at the wellhead.

