

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2024

Submitted Date:

10/06/2024

Document Number:

693807751

**FIELD INSPECTION FORM**Loc ID 315737 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist
Devine, Ellice		ellice.devine@state.co.us	
Saint, John		jsaint@scoutep.com	Regional Manager
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231476	WELL	SI	06/01/2024	ERIW	103-09146	EMERALD 90X	SI

**General Comment:**

UIC-MIT. Verification of repairs. Replace packer

**Location****Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	970-675-3700		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	WAG skid		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 231476

Type: WELL

API Number: 103-09146

Status: SI

Insp. Status: SI

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube: Pressure or inches of Hg

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: WEBR

TC: Pressure or inches of Hg

Previous Test Pressure

Last MIT: 10/16/2019

Brhd: Pressure or inches of Hg

Previous Test Pressure

AnnMTReq:

Comment:

Corrective Action:

Date:

Method of Injection:

Test Type: Verification of Repairs

Tbg psi: 0

Csg psi: 1350

BH psi: 80

Insp. Status: Pass

Comment:

UIC-MIT. Verification of repairs. Replace packer  
Form 42 Doc#403925497 received 9/18/2024, with test scheduled for 10/3/2024.  
Pressure well to 1350 psi. Hold for 15 min. Final pressure 1335 psi. -15 psi loss. OK  
Test witnessed by ECMC using chart on test truck.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807761	Inspection photos 10/3/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6735219">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6735219</a>