

Inspection Photos
Location: Manway 13-32, Manway 13-32 TR
Location ID: 307392
API # 05-071-06371, TR 05-071-06773



Photo 1 – Well placard on meter house, WDID stickers illegible

Photo 2 – KV wellhead

Inspection Photos

Location: Manway 13-32, Manway 13-32 TR

Location ID: 307392

API # 05-071-06371, TR 05-071-06773



Photo 3 – Stained soils

Photo 4 – CDPHE Permitted Outfall

Inspection Photos

Location: Manway 13-32, Manway 13-32 TR

Location ID: 307392

API # 05-071-06371, TR 05-071-06773



Photo 5 – TR wellhead

Photo 6 – Pit Facility ID 256702

Inspection Photos

Location: Manway 13-32, Manway 13-32 TR

Location ID: 307392

API # 05-071-06371, TR 05-071-06773



Photo 7 – Pit Facility ID 256702



Photo 8 – Pit Fencing Inadequate



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources