

# Interim Reclamation and Stormwater Inspection

Date: 09/30/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312229

Inspection Document #: 708201670

Logan County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Photo 1.** Erosion degradation south of the production facilities.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 2.** Erosion degradation south of the production facilities.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 3.** Erosion degradation along the access near production facilities. Straw wattles is now considered debris and needs to be removed.



**Photo 4.** Undesirable vegetation and erosion degradation observed within the pit berm area.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 5.** Continued from Photo 4; photo illustrates sediment transport.



**Photo 6.** Continued from Photo 5; photo illustrates erosion degradation and sediment transport.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 7.** Continued from Photo 6; photo illustrates erosion degradation and sediment transport.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 8.** Undesirable vegetation observed around pit.



**Photo 9.** Erosion degradation on north side of pit.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 10.** Undesirable vegetation observed on north side of pit area.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 11.** Erosion degradation observed on northside of meter shed.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



Photo 12. Continued from Photo 11.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 13.** Continued from Photo 12; sediment deposition observed.

Inspection Photos  
Location Name: Propst B3X  
Location ID: 312229



**Photo 14.** Erosion degradation observed along the access road, north of the production facilities.